

INTERLAB

Tel: +331 3971 7337 – Fax: +331 3928 9008

ISSUE: Lightworks with Matrox HW render issues

Concerned platforms: New LW under Windows7 32 or 64 or XP

Vernouillet, 31.07.2011

Issue : **Render error with systems equipped with Matrox I/O cards**

DSX hardware and VFW software codecs conflicts on who should be doing the render. Solution disable the SW codecs and let the hardware do it.

- Click Start
- Type: **regedit** into the search box
- Make your way to this registry key:
HKEY_LOCAL_MACHINE\SOFTWARE\Wow6432Node\Lightworks\Configuration
- Right click, select New, then select String Value
- Type: **loadMatroxCodecs** (case sensitive) and press Enter
- Double click the new entry and type: **0** as the value
- Close regedit and restart Lightworks

Thank you Mat.

Pls. send us your feel back. Rev.1 – David 31.07.2011