

INTERLAB

Tel: +331 3971 7337 – Fax: +331 3928 9008

ISSUE: hardware enabling register switch in Lightworks 10

Concerned platforms: New LW 10.0.x

Vernouillet, 04.1.2012

Issue : Application do not talk to the hardware.

IMPORTANT REGISTRY ENTRY

On all Lightworks systems that have hardware installed, it is vital that this entry is added

- Click Start
- Type: regedit into the search box
- Make your way to this registry key:
HKEY_LOCAL_MACHINE\SOFTWARE\Lightworks\Configuration
- Right click, select New, then select String Value
- Type: **loadMatroxCodecs** (case sensitive) and press Enter
- Double click the new entry and type: 0 as the value
- Close regedit and restart Lightworks

David 03. 01.2012