

INTERLAB

Tel: +331 3971 7337 – Fax: +331 3928 9008

ISSUE: Matrox Digisuite operation without SDI Module

Concerned platforms:
TOUCH W2K

Issue:

Not certain about Genlock or SDI troubles. Touch Digisuite is made of two module; main Matrox Digisuite LE PCI board and small add-one module containing SDI i/o and Genlock this module is also independently powered.

Normally Lightworks Touch is not designed to run without this SDI Module, however you can for testing purposes force the software to ignore this module.

Here is the step to follow:

- exit Touch application
- with Explorer go to: **c:/Program Files/Lightworks/Touch**
- edit **CONFIG.DAT** file
- add **"No_SDI_module 1"**

Once Module is repaired and mounted do not forget to turn this line into:

"No_SDI_module 0"

Or just remove it.

Pls. send us your feel back.
Rev.1 – David 08.12.06