

INTERLAB

Tel: +331 3971 7337 – Fax: +331 3928 9008

ISSUE: TYAN MB S2895 conflicts QLA2460

OS : WINDOWS
SECIFIC TO TYAN S2895 AMD Chipsets
Located in ALACRITY and VIT

Vernouillet, 29.11.07

Issue:

Conflict with Qlogic QLA-2460 boards. System looks normal but after render or copy process hangs. System is still alive but unstable. QLA board is locked and needs a reboot... Exchanging it with a QLA-2340 makes it work.

Solution:

Update PCI-X driver. Original driver have problem with 266MHz QLA board.

Source:

AMD web site; driver location:

http://cdrom.amd.com/21860/updates/opteron_drivers/english/PCI-X/1.4.4.0/Setup.exe

Driver is also available in our site:

http://www.interlab-net.com/docs/lightworks/support/TYAN_MB_%20S2895_conflicts_QLA2460.zip

This package is not delivered by Tyan in driver pack and needs to be installed after Tyan package. If you will be installing a new package and after you get this behaviour, remember this case...

Special thanks to Filip!

Pls. send us your feel back.
Rev.1.0 – David