

# INTERLAB

Tel: +331 3971 7337 – Fax: +331 3928 9008

## ISSUE: VERTICAL STRIPES ON DISPLAY MONITOR.

Vernouillet, 17.03.2003

We came across a display issue on ONE OF THE TWO display, When you connect NEC TFT 1920NX display on left monitor you get stripes, replacing the monitor by an EIZO... The issue goes away.

After a close look, the interference is generated by the Matrox G440 Board. Left are Right monitor setting was not symmetrical. One refresh rate was set to 60 and the other at 70. Setting refresh rate to BOTH Channel at the same rate SORTS THE ISSUE.

Go to the Matrox system panel and set both to the same rate 60 or 70Hz

Pls. send us your feel back.  
Rev.0 – David 14.03.03