

INTERLAB

Tel: +331 3971 7337 – Fax: +331 3928 9008

ISSUE: can't run Lightworks without audio subsystem

Concerned platforms:

LIGHTWORKS, LIGHTWORKS TURBO
HEAVYWORKS, HEAVYWORKS TURBO
VIP4500

Vernouillet, 09.01.2006

ISSUE & SITUATION:

You are about to release your work and the Lightworks application refuse to start, DEBUG monitor displays an AUDIO SUBSYSTEM ERROR like: *Can't initialize XACT or Audio DSP or ProSound not present or an message of this kind.*

This means that your external Audio Processing is either disconnected or damaged. To be able to start your Lightworks application and make a backup of the project, move material to an other system, render your EDL or film cutting list, here is a way to FORCE your application and ignore the AUDIO ISSUE.

Attention: this does not mean that you solved your problem, and the application will be affected by the hardware status.

SOLUTION:

Find your file: **CONFIG.DAT**. Located in c:/LWORKS or c:\HEAVYWORKS...

Add at the end and before : “} config”:

```
....
audio.daemon.enabled 1
cel_cache_size 2000000
##### Inglore Prosound detection #####
dont_splat_on_xact_init_error 1
} config
```

Restart the application.

Do not forget to remove this line soon your hardware is back in business.

Pls. send us your feel back.
Rev.0 – David 09.01.06