

VIP IS REFUSING TO RECORD WHILE YOU STILL HAVE STORAGE PLACE.

Problem is that PROFILE software running under the Lightworks, is limited to 2.500 entries by default.
So even if you have still room on disks, recording sub-system can refuse to record.

Solution:

Check the number of files in the c:\pdrmovie_db directory structure. If that number is large (close to 2500), you may have reached the set limit of clips for your system.

The number of clips on a system is limited by a registry entry. If you need to record more clips, you can use regedt32.exe to increase that limit.
The limit is set by Max Movies under:

HKEY_LOCAL_MACHINE:
\Software\Tektronix\Profile\PdrMovie key.

Look for : Max_media_references = 2500 / expressed in HEXADECIMAL Values.
Change it to 3500 or 4000...

If you create complex movies (masters) from applications such as the Tool Box Editor, you may also have to modify Max Media References

WARNING : REGEDIT is a dangerous toy, if you are not certain about what you are doing better backup!